



VOLKSWAGEN PASSAT: 1KHV125

Vinnumber:	WVWZZZ3CZFE497312	Versionname:	1.6 TDI TRENDLINE
First Registrationdate:	7/05/2015	Fiscalpower:	
Expertise Mileage:	166390	Power Kw:	88
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4202
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/95 V LightMetal			
Summer tyres:	Fr.L.	Kleber: 3 mm	Fr.R.	Kleber: 3 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	653,16
-------------------	---------------

Bonnet, Dent(s), Acceptable	0,00
-----------------------------	-------------

No pictures to display

Wing R R, Dent(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Wing F L, Dent(s), It - Spot repair	115,56
-------------------------------------	---------------



Door R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Door panel F L, Hole, E - Replace 114,00



Ignition key, Missing, E - Replace 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

