



FORD Grand C-Max: 1HAB009

Vinnumber:	WFOHXXWPBHET14194	Versionname:	GR.C-MAX Titanium St/St 115PK
First Registrationdate:	2/06/2014	Fiscalpower:	
Expertise Mileage:	166270	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	LCV
Maintenance:	GEEN MELDING		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

245/55/16/93 V LightMetal				
Summer tyres:	Fr.L.	Firestone: 5 mm	Fr.R.	Firestone: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	205,00
-------------------	---------------

Aerial, Broken, E - Replace	15,00
-----------------------------	--------------



Door R R, Bad repair, P - Check 0,00



Wing R R, Repaired, Acceptable 0,00



Door panel F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Bad repair, P - Check 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Bad repair, P - Check 0,00



Rear window, Scratch(es), Acceptable 0,00



Bumper F M, Scratch(es), Acceptable 0,00

No pictures to display

Backrest cover F L, Worn, Acceptable 0,00

No pictures to display

Door F L, Bad repair, P - Check 0,00

