



**BMW 3: HK4016**

Vinnumber:	<b>WBA3Y11060D449232</b>	Versionname:	<b>3 GRAN TURISMO 318d 143PK</b>
First Registrationdate:	<b>18/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>188403</b>	Power Kw:	<b>105</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>		
Maintenance:	<b>OK</b>		
Maintenance:	<b>IN 41000 KM</b>		
Battery functioning:	<b>No</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Tires wear profile	<b>OK</b>	Battery functioning	<b>No</b>
Engine startingtime	<b>NOT OK</b>	Clutch test	<b>OK</b>
Handbrake	<b>OK</b>	Wiper fluid level	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/55/17/97 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>1299,15</b>
<b>Alloy rim R L, Scratch(es), LI - Repair and paint (complete)</b>	<b>95,00</b>



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Interior, Dirty, Acceptable

0,00



Bodywork, Accident, No repair

0,00

*No pictures to display*

Door R R, Dent(s), Acceptable

0,00

*No pictures to display*

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Protection plate M, Hole, E - Replace

44,60



Tires, Not original part, Acceptable

0,00

*No pictures to display*

Door frame R L, Dent(s), It - Spot repair

115,56



Dashboard, Scratch(es), Smart repair

110,64



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Door R L, Scratch(es), Acceptable

0,00

*No pictures to display*