



AUDI A3: 1GSG511

Vinnumber:	WAUZZZ8V6EA171240	Versionname:	A3 SB Ambiente 105PK
First Registrationdate:	15/04/2014	Fiscalpower:	
Expertise Mileage:	158549	Power Kw:	77
Bodytype:		Body color:	.
Gearbox:	MAN 6 VIT	Body color:	Brown
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Battery functioning:	Yes	Oil level:	OK
Number of doors:	5	Parking lot:	3528
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting		Headlighting Halogen	
Type of GPS		GPS big screen color	
Type of Lining		Lining semi-artificial leather	
Type of climate control		Autom climate control	
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Fulda: 6 mm	Re.R.	Fulda: 6 mm

Assistance equipment

Spare wheel	Yes	Compressor	Yes
Repair kit	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	654,80
-------------------	---------------

Wing R R, Dent(s), Acceptable	0,00
-------------------------------	-------------



Tailgate, Dent(s), PDR - Paintless dent repair

63,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Door R R, Dent(s), Acceptable

0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Dent(s), Acceptable

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

