



BMW 1 HATCH: 1KHN437

Vinnumber:	WBA1V910205B14562	Versionname:	1.5 116D EFFICIENTDYNAMICS EDIT. (85KW)
First Registrationdate:	6/05/2015	Fiscalpower:	
Expertise Mileage:	133734	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	12000KM	Parking lot:	4205
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	963,90
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Alloy rim F L, Scratch(es), Acceptable

0,00



Alloy rim R L, Scratch(es), Acceptable

0,00



Door F L, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R L, Scratch(es), Acceptable

0,00



Door R R, Dent(s), Acceptable

0,00



Windscreen, Stone chip(s), Windscreen repair

58,80



Seat cover F L, Worn, Acceptable

0,00



Roof, Chemical pollution, LI - Repair and paint (complete)

481,50

