




BMW X4: KP7768			
Vinnumber:	WBAXX110300R41728	Versionname:	2.0 XDRIVE20D (140KW) 4WD
First Registrationdate:	4/01/2016	Fiscalpower:	
Expertise Mileage:	132714	Power Kw:	140
Bodytype:	SUV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/60/17/99 Y LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	No
Total cost ex VAT			336,96
Bonnet, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Door F R, Dent(s), PDR - Paintless dent repair			82,80



Compressor, Missing, E - Replace

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display