



DS 5: 1PLD138

Vinnumber:	VF7KFAHWTF522266	Versionname:	2.0 BLUEHDI 180 S/S SPORT CHIC AUTO
First Registrationdate:	1/08/2016	Fiscalpower:	
Expertise Mileage:	103920	Power Kw:	133
Bodytype:		Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2508
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Xenon	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/45/18/98 Y LightMetal				
Summer tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Other: 3 mm	Re.R.	Other: 3 mm

Assistance equipment

	Compressor	Yes
Total cost ex VAT		892,99
Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)		115,56



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F R, Scratch(es), Acceptable

0,00

No pictures to display

Protection plate M, Tear, E - Replace

74,00



Door F L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08




Alloy rim F L polished, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Door R L, Scratch(es), Acceptable

0,00

No pictures to display