



<b>BMW X3: 1KCD436</b>			
Vinnumber:	<b>WBAWZ310200F64782</b>	Versionname:	<b>2.0 SDRIVE18D (100KW)</b>
First Registrationdate:	<b>30/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>77283</b>	Power Kw:	<b>100</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Dark Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3603</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>Tow bar fixed</b>
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>225/60/17/99 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Dunlop: 7 mm</b>	Fr.R.	<b>Dunlop: 7 mm</b>
	Re.L.	<b>Dunlop: 4 mm</b>	Re.R.	<b>Dunlop: 4 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>20,00</b>
Bonnet, Chemical polution, LI - Repair and paint (complete)			<b>0,00</b>




Bumper R, Scratch(es), LI - Repair and paint (complete) 0,00



Door F R, Dent(s), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 0,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Backrest cover F L, Worn, Acceptable 0,00



Wing F L, Chemical polution, 67 - Polish 0,00

No pictures to display

Rear wiper blade, Damaged, E - Replace 20,00

