



MERCEDES CLA SHOOTING BRAKE: 1KJA097

Vinnumber:	WDD1179081N226625	Versionname:	2.1 CLA 200 CDI SHOOTING BRAKE
First Registrationdate:	8/05/2015	Fiscalpower:	
Expertise Mileage:	113263	Power Kw:	100
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OVER 213 DAGEN	Parking lot:	4525
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	NOT OK	Sound engine	NOT OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	602,16
-------------------	---------------

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Sill outer R, Scratch(es), It - Spot repair	115,56
---	--------



Door F L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Engine, Not functioning (well), P - Check	0,00
---	------

No pictures to display

Wing R R, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------

