



BMW 1 HATCH: 1JVD446

Vinnumber:	WBA1C11020J838800	Versionname:	2.0 118D (100KW)
First Registrationdate:	4/03/2015	Fiscalpower:	
Expertise Mileage:	111440	Power Kw:	100
Bodytype:		Body color:	Orange
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3704
Maintenance:	13000KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 711,00

Door F L, Dent(s) and scratch(es), Acceptable 0,00



Windscreen, Repaired, P - Check

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Door R L, Dent(s), Acceptable

0,00



Bumper R, Scratch(es), 67 - Polish

0,00



Door R R, Scratch(es), Acceptable

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), Acceptable

0,00



Door F R, Scratch(es), Acceptable

0,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

404,20

