



CITROEN C4 CACTUS: 1KUP389

Vinnumber:	VF70BBHY3FE530410	Versionname:	1.6 BLUEHDI 100 BUSINESS GPS
First Registrationdate:	7/07/2015	Fiscalpower:	
Expertise Mileage:	78688	Power Kw:	73
Bodytype:	Hatchback	Body color:	Red
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2406
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1887,97
Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)	301,68



Wing R R, Dent(s), PDR - Paintless dent repair

63,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Rear spoiler, Chemical polution, LI - Repair and paint (complete)

115,56



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F L, Bad repair, Acceptable

0,00




Wing moulding F R, Scratch(es), E - Replace

14,40



Bonnet, Chemical polution, LI - Repair and paint (complete)

314,08





Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing moulding F L, Scratch(es), E - Replace

14,40



Wing F R, Scratch(es), Acceptable

0,00

No pictures to display


Bumper spoiler F, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete)

577,50



Wing trim R R, Scratch(es), Acceptable

0,00

No pictures to display

