



BMW 3: 1JGF714

Vinnumber:	WBA3Y11090D451184	Versionname:	3 GRAN TURISMO 318d 136PK
First Registrationdate:	10/12/2014	Fiscalpower:	
Expertise Mileage:	155017	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	BINNEN 28000KM	Parking lot:	4324
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Rear parking sensors	
GPS storage			
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			2679,43
Wing R L, Scratch(es), LI - Repair and paint (complete)			308,20



Door seal R, Broken, E - Replace

62,70



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Floor covering R, Burned, E - Replace

252,00



Alloy rim F R, Scratch(es), Acceptable

0,00



Floor covering F L, Burned, E - Replace

252,00



Bumper R, Dent(s) and scratch(es), Le - Replace and paint

651,00



Door R R, Bad repair, LI - Repair and paint (complete)

318,35



Wing R R, Bad repair, LI - Repair and paint (complete)

308,20



Tailgate, Dent(s), Acceptable

0,00



Wing F L, Scratch(es), LI - Repair and paint (complete)

220,18

