



BMW 3: 1GAP385

Vinnumber:	WBA3K910X0F933201	Versionname:	3 TOURING 316d 116PK
First Registrationdate:	9/12/2013	Fiscalpower:	
Expertise Mileage:	100028	Power Kw:	85
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1117
Maintenance:	SERVICE IN 3000KM 8 2020		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 W LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1490,88
-------------------	----------------


Door F R, Scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



GPS, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Sill trim R, Dent(s), Acceptable 0,00

No pictures to display

Door R R, Dent(s), LI - Repair and paint (complete) 318,35



Door panel F L, Tear, E - Replace 114,00

