



**MERCEDES CLA SHOOTING BRAKE: 1KHZ626**

Vinnumber:	<b>WDD1179081N224906</b>	Versionname:	<b>2.1 CLA 200 CDI SHOOTING BRAKE</b>
First Registrationdate:	<b>8/05/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>63536</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Burgundy</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>B5 IN 119 DAGEN</b>	Parking lot:	<b>4328</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>SD</b>	Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining semi-leather</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>1947,60</b>
<b>Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>366,35</b>



Bonnet, Dent(s), PDR - Paintless dent repair

63,00



Reversible boot mat, Dirty, Cleaning

25,00



Roof, Dent(s), Acceptable

0,00

No pictures to display

Door frame R R, Scratch(es), Acceptable

0,00

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair

110,64



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F R, Scratch(es), It - Spot repair

115,56



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

356,20



Roof, Chemical pollution, LI - Repair and paint (complete)

481,50



Door R L, Dent(s), LI - Repair and paint (complete)

366,35



Roof pillar R, Dent(s), Acceptable

0,00

No pictures to display

Tailgate, Dent(s), PDR - Paintless dent repair

63,00



Windscreen, Repaired, P - Check

0,00

