



BMW X3: 1KLC798

Vinnumber:	WBAWZ310200F65091	Versionname:	2.0 SDRIVE18D (110KW)
First Registrationdate:	26/05/2015	Fiscalpower:	
Expertise Mileage:	60379	Power Kw:	110
Bodytype:	SUV	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1229
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/60/17/99 V LightMetal				
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment


Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Total cost ex VAT	3048,81
--------------------------	----------------

Alloy rim R L, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	382,02
--	---------------



Trunk lid covering R, Broken, Acceptable

0,00



Roof, Chemical polution, LI - Repair and paint (complete)

577,80



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Ignition key, Missing, E - Replace

150,00

No pictures to display


Spoiler R, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Scratch(es), LI - Repair and paint (complete)

382,02



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

362,02



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

369,84



Bonnet, Chemical polution, LI - Repair and paint (complete)

348,09



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display