



**FORD FOCUS CLIPPER: 1PFC836**

Vinnumber:	<b>WF06XXGCC6GG62150</b>	Versionname:	<b>1.5 TDCI 77KW S/S ECON 88G BUSINESS ED</b>
First Registrationdate:	<b>21/06/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>88001</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2513</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 V Steel</b>				
Summer tyres:	Fr.L.	<b>Semperit: 7 mm</b>	Fr.R.	<b>Semperit: 7 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

<b>Total cost ex VAT</b>	<b>1855,72</b>
<b>Bumper R, Scratch(es), Smart repair</b>	<b>110,64</b>



Rear window, Scratch(es), E - Replace

0,00



Wheel cover R R, Deformed / Strained, E - Replace

30,00



Door F R, Scratch(es), Acceptable

0,00


No pictures to display

No pictures to display

Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wheel cover F R, Scratch(es), E - Replace 30,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Tailgate, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Bonnet, Scratch(es), 67 - Polish 0,00

No pictures to display

Maintenance book, Missing, E - Replace 0,00

No pictures to display