


FORD C-MAX: 1KLE676

Vinnumber:	WF0JXXGCBJFC08780	Versionname:	1.6 TDCI 85KW S/S TREND STYLE
First Registrationdate:	26/05/2015	Fiscalpower:	
Expertise Mileage:	49456	Power Kw:	85
Bodytype:	Hatchback	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	OK		
Maintenance	GEEN INDICATIE		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/16/93 V LightMetal				
Summer tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 7 mm	Re.R.	Vredestein: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT		2085,22
Door F L, Scratch(es), LI - Repair and paint (complete)		318,35



Bumper F, Not original part, Acceptable

0,00



Maintenance book, Missing, P - Check

0,00



Door R R, Scratch(es), Acceptable

0,00



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18



Door panel F L, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper F, Scratch(es), Acceptable

0,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

366,35



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

414,35



Grill, Broken, E - Replace

343,63



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Scratch(es), It - Spot repair

115,56

