


MERCEDES A: 1LHE377

Vinnumber:	WDD1760121V104922	Versionname:	1.5 A 180 CDI AMG LINE
First Registrationdate:	28/09/2015	Fiscalpower:	
Expertise Mileage:	56797	Power Kw:	80
Bodytype:		Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4301
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather and alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/40/18/92 V LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	No	Compressor	No
Total cost ex VAT			1198,96
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)			95,00



Compressor, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Tyre repair kit, Missing, E - Replace	210,53



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------




Door F R, Scratch(es), LI - Repair and paint (complete)	0,00
---	------



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Wing F R, Scratch(es), LI - Repair and paint (complete)	0,00
---	------



Wing R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------

