



BMW 3 BERLINE: 1KTA956

Vinnumber:	WBA3D11030F397669	Versionname:	2.0 318D (105KW) BERLINE
First Registrationdate:	26/06/2015	Fiscalpower:	
Expertise Mileage:	66259	Power Kw:	105
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1ST VERDIEP STEENTJES
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Sun Roof electric	
Windows electric R		Central consol F	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/18/91 H LightMetal				
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	2487,86
Wing F R, Dent(s), PDR - Paintless dent repair	63,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim F L polished, Scratch(es), E - Replace

235,20



Alloy rim F R polished, Scratch(es), E - Replace

235,20



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim R R polished, Scratch(es), E - Replace

235,20



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R L polished, Scratch(es), E - Replace 235,20

