



PEUGEOT BOXER: 1DSD738

Vinnumber:	VF3YC2MFB12C98267	Versionname:	2.0 BlueHDi SS 130 Premium Pack 335 L2H2
First Registrationdate:	22/03/2017	Fiscalpower:	
Expertise Mileage:	48328	Power Kw:	96
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV20
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/70/15/109 S Steel				
Summer tyres:	Fr.L.	Dunlop: 9 mm	Fr.R.	Dunlop: 9 mm
	Re.L.	Continental: 8 mm	Re.R.	Continental: 8 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	728,90
Wheel cover R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	238,76



Rearlight R , Broken, E - Replace 91,50



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror L complete, Broken, E - Replace 138,00



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00

No pictures to display

Bumper F L, Scratch(es), Smart repair 110,64

