



BMW 3: 1GTA535			
Vinnumber:	WBA3Y31060D644713	Versionname:	3 GRAN TURISMO 320d 163PK
First Registrationdate:	22/04/2014	Fiscalpower:	
Expertise Mileage:	179427	Power Kw:	120
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2808
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Summer tyres:	225/55/17/97 W LightMetal		
	Fr.L.	Fr.R.	Continental: 6 mm
	Re.L.	Re.R.	Continental: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			946,28
Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)			211,80





Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Dent(s), PDR - Paintless dent repair 63,00



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 301,68



Roof, Dent(s), PDR - Paintless dent repair 63,00



Door R L, Scratch(es), 67 - Polish 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

