


PEUGEOT PARTNER TEPEE: 1NCD278

Vinnumber:	VF37JBHY6FJ883131	Versionname:	1.6 BLUEHDI 73KW S/S TEPEE STYLE
First Registrationdate:	18/01/2016	Fiscalpower:	
Expertise Mileage:	168273	Power Kw:	73
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	GEEN MELDING	Parking lot:	3703
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Cruise Control		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	No Tow bar
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/65/15/94 H Steel			
Winter tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	809,19
-------------------	--------

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bodywork, Glue residues, Acceptable	0,00
-------------------------------------	------

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair	110,64
---	--------



Engine protective plate, Hole, Acceptable 0,00

No pictures to display

Bonnet, Scratch(es), 67 - Polish 0,00



Interior, Stain, Cleaning 75,00



Ignition key, Not functioning (well), E - Replace 150,00



Windscreen, Stone chip(s), Windscreen repair 0,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 231,15



Gear shift lever cover, Worn, Acceptable 0,00

No pictures to display

Bumper F R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Dent(s), PDR - Paintless dent repair 242,40





Door panel F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Ceiling, Deformed / Strained, Acceptable	0,00
<i>No pictures to display</i>	