



**BMW 4 GRAN COUPE: 1KPG820**

|                                    |                          |              |                                    |
|------------------------------------|--------------------------|--------------|------------------------------------|
| Vinnumber:                         | <b>WBA4E91070G283524</b> | Versionname: | <b>2.0 420D (120KW) GRAN COUPE</b> |
| First Registrationdate:            | <b>9/06/2015</b>         | Fiscalpower: |                                    |
| Expertise Mileage:                 | <b>96769</b>             | Power Kw:    | <b>120</b>                         |
| Bodytype:                          | <b>Berline</b>           | Body color:  | <b>Silver</b>                      |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                     |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>                   |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                          |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>4504</b>                        |
| Number of doors:                   | <b>5</b>                 |              |                                    |
| Number of seats:                   | <b>5</b>                 |              |                                    |
| Number head rests:                 | <b>4</b>                 |              |                                    |
| Rims summer:                       | <b>Aluminium</b>         |              |                                    |
| Category:                          | <b>Passenger Car</b>     |              |                                    |
| Oil level:                         | <b>OK</b>                |              |                                    |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                    |

**Options**

|                                |                              |                       |                      |
|--------------------------------|------------------------------|-----------------------|----------------------|
| Radio CD                       |                              | Central consol F      |                      |
| GPS storage                    |                              | Luggage cover         |                      |
| GPS storage                    | <b>HD</b>                    | Front parking sensors |                      |
| Windows electric F             |                              | Rear parking sensors  |                      |
| Windows electric R             |                              | Type of Tow bar       | <b>Tow bar fixed</b> |
| Cruise Control                 |                              |                       |                      |
| Steering wheel multifunctional |                              |                       |                      |
| Seats F heated                 |                              |                       |                      |
| Radio multimedia               |                              |                       |                      |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                       |                      |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                      |
| Type of Lining                 | <b>Lining leather</b>        |                       |                      |
| Type of climate control        | <b>Autom climate control</b> |                       |                      |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                       |       |                       |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| <b>225/45/18/91 Y LightMetal</b> |       |                       |       |                       |
| Summer tyres:                    | Fr.L. | <b>Goodyear: 5 mm</b> | Fr.R. | <b>Goodyear: 5 mm</b> |
|                                  | Re.L. | <b>Goodyear: 5 mm</b> | Re.R. | <b>Goodyear: 5 mm</b> |

**Assistance equipment**

|  |          |
|--|----------|
| Number of charging cables (normal)       | <b>0</b> |
| Number of charging cables (rapid charge) | <b>0</b> |

|                          |               |
|--------------------------|---------------|
| <b>Total cost ex VAT</b> | <b>898,37</b> |
|--------------------------|---------------|

|                                       |             |
|---------------------------------------|-------------|
| <b>Door R R, Repaired, Acceptable</b> | <b>0,00</b> |
|---------------------------------------|-------------|

|  |             |
|--|-------------|
| <i>No pictures to display</i>            |             |
| <b>Bonnet, Stone chip(s), Acceptable</b> | <b>0,00</b> |

|                               |  |
|-------------------------------|--|
| <i>No pictures to display</i> |  |
|-------------------------------|--|

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

264,21



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Tailgate, Scratch(es), Acceptable

0,00

*No pictures to display*

Bumper R, Scratch(es), Acceptable

0,00

*No pictures to display*

Roof pillar R, Repaired, Acceptable

0,00

*No pictures to display*

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00





Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00

