



**AUDI A3 SPORTBACK: 1KUV472**

Vinnumber:	<b>WAUZZZ8V8GA005630</b>	Versionname:	<b>1.6 TDI ULTRA ATTRACTION SPORTBACK</b>
First Registrationdate:	<b>8/07/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>100143</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>1313</b>
Maintenance:	<b>17600KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Firestone: 6 mm</b>	Fr.R.	<b>Firestone: 6 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT 1735,06

Wing F L, Scratch(es), LI - Repair and paint (complete) 0,00



Roof, Scratch(es), LI - Repair and paint (complete)

481,50



Door R R, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Door F L, Scratch(es), LI - Repair and paint (complete)

318,35



Door F R, Scratch(es), Acceptable

0,00



Roof pillar R, Scratch(es), LI - Repair and paint (complete)

220,18



Wing R L, Scratch(es), LI - Repair and paint (complete)

0,00



Tailgate, Scratch(es), LI - Repair and paint (complete)

301,68

