



**CITROEN GRAND C4 PICASSO: 1KJF303**

Vinnumber:	<b>VF73EAHRMFJ651853</b>	Versionname:	<b>2.0 BLUEHDI 150 MAN6 EXCLUSIVE</b>
First Registrationdate:	<b>11/05/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>114738</b>	Power Kw:	<b>110</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2226</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage	<b>HD</b>	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Type of Tow bar	<b>Tow bar removable</b>
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining semi-artificial leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/17/95 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Pirelli: 6 mm</b>	Fr.R.	<b>Pirelli: 6 mm</b>
	Re.L.	<b>Pirelli: 6 mm</b>	Re.R.	<b>Pirelli: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>3449,26</b>
<b>Wing R R, Dent(s) and scratch(es), Le - Replace and paint</b>	<b>1231,51</b>



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R R, Missing, E - Replace 20,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Dent(s) and scratch(es), Le - Replace and paint 946,92



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Engine protective plate, Deformed / Strained, E - Replace 30,00



Protection plate M, Deformed / Strained, E - Replace 74,00




Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Wheel hub cap F L, Missing, E - Replace 30,00



Bonnet, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
	
Sill outer R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	