


**AUDI A3: 1FFD380**

Vinnumber:	<b>WAUZZZ8V6DA085523</b>	Versionname:	<b>A3 SB Attraction 105PK</b>
First Registrationdate:	<b>12/06/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>114451</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1330</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>SD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 W LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 6 mm</b>	Re.R.	<b>Continental: 6 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	1774,49
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80



Door R L, Dent(s), PDR - Paintless dent repair

63,00



Windscreen, Stone chip(s), Windscreen repair

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Rear window, Scratch(es), Acceptable

0,00







Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)

290,08



Boot cover, Broken, E - Replace

50,00



Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Rocker panel inner R R, Dent(s), Acceptable

0,00

No pictures to display

Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)

115,56



Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Door F R, Dent(s), Acceptable

0,00

No pictures to display

Door R R, Chemical polution, LI - Repair and paint (complete)

318,35





Bumper grille, Scratch(es), E - Replace

32,40

