



CITROEN Berlingo: PW1278

| | | | |
|-------------------------|---------------------------------|--------------|-----------------------------------|
| Vinnumber: | VF77B9HN0DN509885 | Versionname: | BERLINGO B/F Kort Pro 75PK |
| First Registrationdate: | 7/05/2013 | Fiscalpower: | |
| Expertise Mileage: | 214713 | Power Kw: | 55 |
| Bodytype: | Transporter | Body color: | White |
| Gearbox: | MAN 5 VIT | Paint type: | Opaque |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | LCV10 |
| Number of doors: | 5 | | |
| Number of seats: | 3 | | |
| Number head rests: | 3 | | |
| Rims summer: | Steel | | |
| Category: | Light Commercial Vehicle | | |
| Oil level: | OK | | |

Options

| | | |
|-------------------------|-----------------------------|-------------------|
| Radio CD | Type of Tow bar | No Tow bar |
| Windows electric F | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | No GPS | |
| Type of Lining | Lining fabrics | |
| Type of climate control | No climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Tires wear profile | OK | Battery functioning | Yes |
| Idle position | OK | Power steering | Yes |
| Engine startingtime | OK | Sound engine | OK |
| Exhaust gass | OK | Clutch test | OK |
| Handbrake | OK | Wiper fluid level | OK |
| | | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------|-------|-----------------------|-------|-----------------------|
| 195/65/15/91 H Steel | | | | |
| Summer tyres: | Fr.L. | Goodyear: 4 mm | Fr.R. | Goodyear: 4 mm |
| | Re.L. | Goodyear: 5 mm | Re.R. | Goodyear: 5 mm |

Assistance equipment

| | |
|--|------------|
| Spare wheel | Yes |
| Number of charging cables (normal) | 0 |
| Number of charging cables (rapid charge) | 0 |

| | |
|---|----------------|
| Total cost ex VAT | 1768,96 |
| Door F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 231,15 |



Trunk door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete) 165,13



Bodywork, Not original part, Acceptable 0,00

No pictures to display

Door panel F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), LI - Repair and paint (complete) 231,15



Rearview mirror R complete, Broken, E - Replace 138,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Trunk door panel L, Broken, E - Replace 64,00



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display


Rearview mirror L complete, Broken, E - Replace 138,00



Door R R, Rust, Acceptable 0,00



Roof, Dent(s), LI - Repair and paint (complete) 361,13



Wheel cover R L, Scratch(es), E - Replace 22,50



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Trunk door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Deformed / Strained, E - Replace 22,50



Windscreen, Stone chip(s), E - Replace

395,40

