



BMW X5: RM9580			
Vinnumber:	WBAKS810600G65713	Versionname:	X5 M 50dAS 381PK Aut.
First Registrationdate:	12/02/2014	Fiscalpower:	
Expertise Mileage:	39145	Power Kw:	280
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4807
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Seats R heated	
TV/DVD screen R		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Seats F L ventilated	
Cruise Control		Seats F R ventilated	
Steering wheel multifunctional		Sun Roof electric	
Seats F heated		Panoramic roof	
Radio multimedia		Central consol F	
Type of headlighting	Headlighting LED	Luggage cover	
Type of GPS	GPS big screen color	Front parking sensors	
Type of Lining	Lining leather	Rear parking sensors	
Type of climate control	Autom climate control	Type of Tow bar	No Tow bar
Head-up Display			

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	315/35/20/110 V LightMetal			
Winter tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment	
Runflat	Yes

Total cost ex VAT	834,16
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00



Trunk lid covering R, Dirty, Cleaning 50,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace

150,00

No pictures to display