


MERCEDES A: 1GSN269

Vinnumber:	WDD1760121V013974	Versionname:	A 180CDI BE Edition 109PK
First Registrationdate:	16/04/2014	Fiscalpower:	
Expertise Mileage:	135889	Power Kw:	80
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Body color	.
Transmission:	Front	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Maintenance	B1 DEPASSE DE 31 JOURS	Oil level	OK
Maintenance	NOT OK	Parking lot	3626
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	1		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		
Windows electric F		
Windows electric R		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-artificial leather	
Type of climate control	Autom climate control	
Level control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	No	Compressor	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2120,41
Maintenance, Maintenance, Execute	0,00



Bonnet, Scratch(es), LI - Repair and paint (complete)

290,08



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Wing R L, Dent(s), PDR - Paintless dent repair

63,00



Tyre repair kit, Missing, E - Replace

210,53



Roof pillar R, Dent(s), PDR - Paintless dent repair

82,80



Roof, Scratch(es), LI - Repair and paint (complete)

481,50



Bumper R, Dent(s) and scratch(es), Le - Replace and paint

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80





Bumper moulding R, Deformed / Strained, E - Replace 0,00



Alloy rim F R, Scratch(es), Acceptable 0,00



Alloy rim R R, Scratch(es), Acceptable 0,00



Tailgate, Scratch(es), Acceptable 0,00



MOT Certificate, Missing, E - Replace 0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete) 0,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 462,35

