



FORD S Max: 1HHL023

Vinnumber:	WF0SXXGBWSEM75561	Versionname:	S-MAX ECO Tit.Style DPF PS 136PK Aut.
First Registrationdate:	24/07/2014	Fiscalpower:	
Expertise Mileage:	160638	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	GEEN MELDING	Parking lot:	1104
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	SD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/99 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Kleber: 6 mm	Re.R.	Kleber: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 2154,71

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 430,02



Wing R R, Scratch(es), LI - Repair and paint (complete)

369,84



GPS, Not functioning (well), P - Check

0,00



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror basis R, Broken, E - Replace

127,07



Bumper corner R L, Scratch(es), It - Spot repair

115,56



Tailgate, Scratch(es), It - Spot repair

115,56



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Dent(s), PDR - Paintless dent repair

82,80



Alloy rim R L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Broken, E - Replace

483,84



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

430,02



