



MERCEDES ML: 1HFL598

Vinnumber:	WDC1660041A422399	Versionname:	ML 250 BlueTEC 204PK Aut.
First Registrationdate:	8/07/2014	Fiscalpower:	
Expertise Mileage:	123778	Power Kw:	150
Bodytype:	SUV	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/65/17/104 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1184,90
Door F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)			0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Reflector, Broken, E - Replace

20,00



Bumper moulding F M, Broken, E - Replace

17,28



Bumper moulding R Mid, Dent(s), E - Replace

17,28



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Interior, Dirty, Cleaning

50,00





Door F L, Scratch(es), LI - Repair and paint (complete)

382,02



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16

