


OPEL Combo Cargo: 1HPP067

Vinnumber:	W0L6VYC1AF9553564	Versionname:	COMBO COMBI SWB St/St(EU5)90PK
First Registrationdate:	5/09/2014	Fiscalpower:	
Expertise Mileage:	170198	Power Kw:	66
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2412
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
Windows electric F		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1850,17
Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror L complete, Broken, E - Replace	138,00



Wing F L, Scratch(es), LI - Repair and paint (complete)

165,13



Rearview mirror R complete, Broken, E - Replace

138,00



Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Bodywork, Not original part, Acceptable

0,00

No pictures to display

Windscreen, Stone chip(s), E - Replace

395,40



Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Seat cover F L, Hole, E - Replace

300,00



Wheel cover R R, Scratch(es), E - Replace

22,50



Wheel cover R L, Scratch(es), Acceptable

0,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Dent(s), Acceptable

0,00

No pictures to display

Tailgate, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Smart repair

110,64



Floor covering F L, Hole, E - Replace

237,00





Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 22,50



Headlight L, Scratch(es), E - Replace 321,00

