



SMART FORFOUR: FW4829

| | | | |
|------------------------------------|--------------------------|--------------|----------------------|
| Vinnumber: | WME4530421Y097006 | Versionname: | 1.0 52KW PURE |
| First Registrationdate: | 19/08/2016 | Fiscalpower: | |
| Expertise Mileage: | 82673 | Power Kw: | 52 |
| Bodytype: | | Body color: | Blue |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Petrol | Oil level: | OK |
| Maintenance: | IN 11100 KM | Parking lot: | 1705 |
| Maintenance: | OK | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 4 | | |
| Number head rests: | 4 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | No | | |

Options

| | | | |
|--------------------------------|------------------------------|----------------------|-------------------|
| Windows electric F | | Luggage cover | |
| Cruise Control | | Rear parking sensors | |
| Steering wheel multifunctional | | Type of Tow bar | No Tow bar |
| Type of headlighting | Headlighting Halogen | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|---------------------------------|---------------------|-------|---------------------|
| | 165/65/15/8 T LightMetal | | | |
| Summer tyres: | Fr.L. | Dunlop: 5 mm | Fr.R. | Dunlop: 5 mm |
| | Re.L. | Dunlop: 4 mm | Re.R. | Dunlop: 4 mm |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|-----------------------------------|---------------|
| Total cost ex VAT | 262,96 |
| Door F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Interior, Stain, Cleaning | 25,00 |



| | |
|--|--------|
| Wing R R, Dent(s), PDR - Paintless dent repair | 122,40 |
|--|--------|



| | |
|-------------------------------------|------|
| Bodywork, Glue residues, Acceptable | 0,00 |
|-------------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Door R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---|--------|
| Door frame F L, Dent(s), It - Spot repair | 115,56 |
|---|--------|

