



<b>RENAULT Grand Scenic: 1EUI398</b>			
Vinnumber:	<b>VF1JZ14A648788082</b>	Versionname:	<b>GR.SCENIC Energ.Business 5pl.FAP 110PK</b>
First Registrationdate:	<b>22/03/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>156377</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Red</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1714</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>205/60/16/96 H Steel</b>			
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

<b>Assistance equipment</b>			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
<b>Total cost ex VAT</b>			<b>2322,14</b>
<b>Bumper R, Deformed / Strained, Le - Replace and paint</b>			<b>651,00</b>





Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Wheel cover F R, Scratch(es), E - Replace 30,00



Rocker panel inner F L, Dent(s), LI - Repair and paint (complete) 115,56



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), PDR - Paintless dent repair 102,60



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Rearview mirror housing R, Broken, LI - Repair and paint (complete) 115,56



Ignition key, Missing, E - Replace 150,00

No pictures to display

Wing F L, Scratch(es), 67 - Polish 0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Roof, Dent(s), Acceptable 0,00

No pictures to display

Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Bonnet, Scratch(es), 67 - Polish 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Rearview mirror housing L, Broken, LI - Repair and paint (complete) 115,56

