



MINI CLUBMAN: 1TGX500			
Vinnumber:	WMWLN310802G31002	Versionname:	Cooper (100 kW)
First Registrationdate:	3/11/2017	Fiscalpower:	
Expertise Mileage:	30906	Power Kw:	100
Bodytype:	Break	Body color:	Green
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3526
Number of doors:	6		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Windows electric F		Sun Roof electric	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		
Head-up Display			
Sport seats			

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/45/17/94 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment	
Total cost ex VAT	905,16
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Bonnet, Chemical polution, 67 - Polish 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80




Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56




Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Le - Replace and paint 292,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Dent(s), Acceptable

0,00

No pictures to display