



VOLKSWAGEN Crafter 35 MWB: 1BEM283

Vinnumber:	WV1ZZZ2FZB7005535	Versionname:	CRAFTER 35 LB2C MWB 109PK
First Registrationdate:	12/05/2011	Fiscalpower:	
Expertise Mileage:	260384	Power Kw:	80
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	6		
Number head rests:	6		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD	Type of Tow bar	Tow bar fixed
Windows electric F		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	
Type of climate control	No climate control	

Limited Technical Inspection

Idle position	OK	Battery functioning	Yes
Engine startingtime	OK	Power steering	Yes
Exhaust gass	OK	Sound engine	NOT OK
Handbrake	OK	Clutch test	NOT OK
		Wiper fluid level	OK
		Transmission	NOT OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/65/16/115 R Steel				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1936,77
-------------------	----------------

Outer door handle R R, Broken, Le - Replace and paint	115,56
---	---------------



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)	217,56
---	---------------



Door R L, Rust, LI - Repair and paint (complete) 238,76



Seat cover F R, Tear, E - Replace 300,00



Bumper F, Dent(s), E - Replace 398,40



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Hole, E - Replace 300,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Central pillar L, Rust, LI - Repair and paint (complete) 366,49

