


**OPEL ASTRA SPORTS TOURER: 1KPC875**

Vinnumber:	<b>WOLPD8E6XF8058947</b>	Versionname:	<b>1.6 CDTI 81KW ECOFLEX S/S ULTIMATE EDITI</b>
First Registrationdate:	<b>8/06/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>165105</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Break</b>	Body color:	<b>Silver</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3503</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar removable</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining semi-artificial leather</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/60/16/95 V Steel</b>			
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	1995,76
-------------------	---------

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Wheel cover R L, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56




Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)

290,08



Seat cover F L, Worn, Acceptable

0,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing R R, Bad repair, Acceptable 0,00



Tailgate, Dent(s), PDR - Paintless dent repair 102,60



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Trunk lid covering R, Crack, Smart repair 110,64





Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80

