



SKODA Octavia: 1GRJ638

Vinnumber:	TMBJG7NE8E0183765	Versionname:	OCTAVIA COMBI Ambition 105PK
First Registrationdate:	8/04/2014	Fiscalpower:	
Expertise Mileage:	131399	Power Kw:	77
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1531
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H Steel				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	350,08
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover R R, Missing, E - Replace	30,00



Roof pillar L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Scratch(es), E - Replace 30,00



Windscreen, Scratch(es), E - Replace 0,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Chemical polition, LI - Repair and paint (complete) 290,08



Rear window, Scratch(es), E - Replace 0,00



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display