



VOLVO S60: 1JLG047

Vinnumber:	YV1FS8481F2353845	Versionname:	1.6 D2 KINETIC
First Registrationdate:	16/01/2015	Fiscalpower:	
Expertise Mileage:	93447	Power Kw:	84
Bodytype:	Berline	Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	LCV
Maintenance:	OVER 8394 KM		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	95,00
-------------------	-------

Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------

No pictures to display

Door panel F R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door panel R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Sill trim R, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display

Wing F R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Rearview mirror R complete, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper R, Bad repair, Paint	0,00
-----------------------------	------



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

No pictures to display

Wing R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display