



VOLVO V60: 1KDV467

Vinnumber:	YV1FW8481F1262359	Versionname:	1.6 D2 KINETIC
First Registrationdate:	10/04/2015	Fiscalpower:	
Expertise Mileage:	43637	Power Kw:	84
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4209
Maintenance:	OVER 19793		
Maintenance:	26/07/2020		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
Windows electric F		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			679,88
Door R L, Scratch(es), Acceptable			0,00



Bumper F, Scratch(es), It - Spot repair

115,56



Bumper R, Scratch(es), 67 - Polish

25,00



Door R R, Scratch(es), It - Spot repair

115,56



Outer door handle R R, Scratch(es), LI - Repair and paint (complete)

115,56



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (partial)

308,20

