



MINI : 1KFG991			
Vinnumber:	WMWXT110702B77319	Versionname:	1.5 ONE D
First Registrationdate:	21/04/2015	Fiscalpower:	
Expertise Mileage:	97349	Power Kw:	70
Bodytype:	Hatchback	Body color:	Green
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3712
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	175/65/15/84 H LightMetal			
Summer tyres:	Fr.L.	Fulda: 6 mm	Fr.R.	Fulda: 6 mm
	Re.L.	Hankook: 6 mm	Re.R.	Hankook: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			834,84
Bumper R, Scratch(es), LI - Repair and paint (complete)			211,80





Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
----------------------------------------	------

No pictures to display

Seat cover R R, Stain, Cleaning	50,00
---------------------------------	-------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--------------------------------------------------------------	-------



Rearview mirror housing L, Scratch(es), Smart repair	110,64
------------------------------------------------------	--------



Roof, Dent(s), PDR - Paintless dent repair	122,40
--------------------------------------------	--------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--------------------------------------------------------------	-------

