



VOLKSWAGEN PASSAT VARIANT: 1LBF855

Vinnumber:	WVWZZZ3CZGE032234	Versionname:	1.6 TDI MSQ VARIANT COMFORTLINE
First Registrationdate:	10/08/2015	Fiscalpower:	
Expertise Mileage:	160600	Power Kw:	88
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	SD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		






Total cost ex VAT	1196,44
--------------------------	----------------

Wing R L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Roof, Scratch(es), Acceptable	0,00
--------------------------------------	-------------

No pictures to display

Door F L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Rocker panel inner R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Grill frame, Broken, E - Replace	175,00
	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
	
Roof pillar R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Trunk lid covering R, Scratch(es), Smart repair	110,64
	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Stone chip(s), E - Replace	487,20
	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	