



AUDI Q5: 1KUF813

Vinnnumber:	WAUZZZ8R0GA008802	Versionname:	2.0 TDI 110KW
First Registrationdate:	6/07/2015	Fiscalpower:	
Expertise Mileage:	110965	Power Kw:	110
Bodytype:	SUV	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1126
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
Adaptive cruise control	
Sport seats	Tow bar fixed

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/60/18/107 W LightMetal				
Summer tyres:	Fr.L.	Vredestein: 8 mm	Fr.R.	Vredestein: 8 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1006,02
-------------------	----------------

Bumper R, Scratch(es), 67 - Polish	0,00
------------------------------------	-------------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16
---	---------------



Door R L, Scratch(es), LI - Repair and paint (complete) 382,02



Wing R L, Scratch(es), LI - Repair and paint (complete) 369,84



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), 67 - Polish 0,00

No pictures to display

Door R R, Scratch(es), 67 - Polish 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display