



AUDI Q3: 1HCA388			
Vinnumber:	WAUZZZ8U9ER102437	Versionname:	Q3 136PK
First Registrationdate:	16/06/2014	Fiscalpower:	
Expertise Mileage:	152645	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4326
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Sun Roof electric	
GPS storage	SD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	235/55/17/99 V LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1208,00
Door moulding Lower F R, Scratch(es), E - Replace			114,00



Wing trim R R, Scratch(es), E - Replace

84,00



Bonnet, Dent(s), Acceptable

0,00



Wing R L, Dent(s), Acceptable

0,00



Trunk lid covering R, Scratch(es), Smart repair

110,64



Wing R R, Dent(s), LI - Repair and paint (complete)

356,20



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Windscreen, Stone chip(s), Acceptable

0,00



Wing F R, Deformed / Strained, Forfeit

48,00



Alloy rim F R, Scratch(es), Acceptable 0,00



Seat cover R, Stain, Cleaning 25,00



Door moulding Lower R R, Scratch(es), E - Replace 114,00



Wing moulding F R, Scratch(es), E - Replace 14,40



Wing moulding F L, Scratch(es), E - Replace 14,40



Bumper F, Scratch(es), It - Spot repair 115,56

