



<b>FORD Focus: 1FKL066</b>			
Vinnumber:	<b>WF0LXXGCBLDA24943</b>	Versionname:	<b>FOCUS CLIP. EConetic Titanium 88g 105PK</b>
First Registrationdate:	<b>26/07/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>118049</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1209</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>			
Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar fixed</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>205/55/16/91 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>1550,57</b>
<b>Bumper F, Scratch(es), Acceptable</b>	<b>0,00</b>
<i>No pictures to display</i>	
<b>Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>308,20</b>



Rear window, Scratch(es), E - Replace

0,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)


308,20



A-pillar right, Scratch(es), LI - Repair and paint (complete)

220,18





Windscreen, Scratch(es), Acceptable

0,00



Tailgate, Crack, Le - Replace and paint

0,00



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), Smart repair

110,64



Brand badge R, Worn, Acceptable

0,00



Door R L, Dent(s) and scratch(es), L L - Repair and paint (complete)

318,35



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Scratch(es), 67 - Polish

0,00

No pictures to display

Door R R, Dent(s), Acceptable

0,00

No pictures to display

Bumper corner R R, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display