



BMW X4: 1LKK867			
Vinnumber:	WBAXX110500R37812	Versionname:	2.0 XDRIVE20D (120KW) 4WD
First Registrationdate:	13/10/2015	Fiscalpower:	
Expertise Mileage:	163013	Power Kw:	120
Bodytype:	SUV	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2304
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Sun Roof electric	
Windows electric F		Central consol F	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	245/50/18/100 W LightMetal			
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment	
Runflat	Yes

Total cost ex VAT	1326,11
Wheel cover F R, Missing, E - Replace	36,00



Rear window, Scratch(es), E - Replace 420,00



Rear spoiler, Scratch(es), 67 - Polish 0,00



Wheel cover R R, Missing, E - Replace 36,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete) 348,09



Protection plate M, Tear, E - Replace 74,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Aerial, Scratch(es), LI - Repair and paint (complete) 50,00



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 362,02

