



LU Volkswagen Golf Variant: RJ6043

Vinnumber:	WVWZZZAUZGP520956	Versionname:	1.6 TDI 81KW HIGHLINE VARIANT
First Registrationdate:	17/08/2015	Fiscalpower:	
Expertise Mileage:	139851	Power Kw:	81
Bodytype:		Body color:	Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	Icv
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

GPS storage		Central consol F
GPS storage	SD	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-Alcantara	
Type of climate control	Autom climate control	
Adaptive cruise control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/17/91 H LightMetal				
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			983,32
Air vent R M, Broken, E - Replace			156,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Scratch(es), Acceptable

0,00



Seat cover F R, Stain, Acceptable

0,00



Bumper F, Scratch(es), It - Spot repair

115,56



Seat cover F L, Stain, Cleaning

25,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Wing R R, Dent(s), LI - Repair and paint (complete)

356,20



Seat cover R, Stain, Cleaning

25,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

