



**AUDI A3: 1HHL017**

Vinnumber:	<b>WAUZZZ8V3FA019644</b>	Versionname:	<b>A3 SB Attraction 110PK</b>
First Registrationdate:	<b>24/07/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>88821</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2328</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Sun Roof electric	
GPS storage	<b>SD</b>	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>Tow bar removable</b>
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining artificial leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 W LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>2722,71</b>
<b>Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>211,80</b>



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Rearview mirror housing R, Scratch(es), Acceptable 0,00

*No pictures to display*

Sill outer L, Dent(s), LI - Repair and paint (complete) 310,50



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 220,18







Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Door F L, Dent(s), Acceptable

0,00

*No pictures to display*

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00




Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Rear spoiler, Scratch(es), Acceptable

0,00

*No pictures to display*

Wing R L, Scratch(es), Acceptable

0,00

*No pictures to display*

Bonnet, Stone chip(s), Acceptable

0,00

*No pictures to display*

Tailgate, Bad repair, Acceptable

0,00

