



FORD Grand C-Max: 1JRD907

Vinnumber:	WFOHXXGCBHEG54618	Versionname:	GR.C-MAX Trend Style S-S 115PK
First Registrationdate:	5/02/2015	Fiscalpower:	
Expertise Mileage:	104358	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1425
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Central consol F	
GPS storage		Rear parking sensors	
GPS storage	SD	Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/16/93 H LightMetal				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1524,75
Windscreen, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Luggage space cover, Missing, E - Replace	240,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 462,35



Trunk lid covering R, Scratch(es), Smart repair 110,64



Bumper F L, Dent(s) and scratch(es), It - Spot repair 115,56



Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Spoiler F L, Deformed / Strained, E - Replace 42,00



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Bad repair, P - Check 0,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 404,20



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Registration Document, Missing, E - Replace 150,00

