


AUDI A6: 1HUP142

Vinnumber:	WAUZZZ4G7EN198639	Versionname:	A6 BER Multitr.136PK Aut.
First Registrationdate:	7/10/2014	Fiscalpower:	
Expertise Mileage:	145137	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2629
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	4293,07
-------------------	----------------

Wing R R, Bad repair, Acceptable	0,00
----------------------------------	-------------

No pictures to display

Sill outer L, Dent(s), LI - Repair and paint (complete)	0,00
---	-------------



Door R R, Scratch(es), LI - Repair and paint (complete) 382,02



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Dent(s) and scratch(es), Le - Replace and paint 0,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 264,21



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), Le - Replace and paint 1270,21





Bonnet, Scratch(es), LI - Repair and paint (complete)

348,09



Ignition key, Missing, E - Replace

150,00



Bumper R, Dent(s) and scratch(es), Le - Replace and paint

766,80

